

GALAXYTM

THE PERFECT GLITTERING HEAT TRANNSFER FILM FOR ACCESSORIES PERSONALISATION

Looking for trendy and smooth touch heat transfer film? Galaxy is a glittering PU that will suit particularly well to the personalisation of fashion and promotional accessories.

Fashion Accessories



Product description

- ✓ Smooth touch with a glitter look → two in one finish.
- ✓ Very small and thin sequins, which allow to achieve a perly/iridescent effect.
- ✓ Great to give 3D effect to your personalisations thanks to its thickness.
- ✓ Available in 10 colours:



Application key points

✓ Very easy to cut thanks its small sequins.

Usage benefits

- ✓ Adapted to medium designs and lettering personalisations.
- ✓ Recommended on fashion accessories and home deco thanks its soft touch feature.
- ✓ Very easy to care, it could be wash up 60°C.







SPECIFICATIONS

Compos	ition	Average Thickness	Carrier	Dimensions
PU		140-200 μm	Adhesive & Transparent Polyester	All references available in: 50 cm x 5 m Ref. 1108, 1107, 1101, 1102, Also available in: 50cm x 20 m

APPLICATION INSTRUCTIONS

Applies on	Cutting Application Temp. & Duratio	
Cotton Polyester Acrylic Cotton/Polyester blends without repellent treatment	Use a Flock Blade 60°	All References: 160°C - 20 s 320°F - 20 s Excepted Reference 1107: 180°C - 20 s 356°F - 20 s

Pressure	Peeling	
Medium	Cold	

Up to 1

year

Step 1 - Cutting

Set up the cutting of your heat transfer film in mirror mode and use a standard flock blade of 60° for the Galaxy.

Step 2 - Weeding

Remove the excess of material (easy weeding).

Step 3 - Application

Position your design on the textile and press it with a Sefa DUPLEX/ROTEX or equivalent at $160^{\circ}\text{C}/320^{\circ}\text{F}$ for 20 seconds, with a medium pressure, except for the reference 1107 ($180^{\circ}\text{C}/356^{\circ}\text{F}$ for 20 seconds).

We do recommend the use of a silicone paper to protect the designs and the textile during the application.

Step 4 - Peeling

Peel the material while cold.

NOTE: We highly recommend you to perform tests before launching a production.

CARE AND MAINTENANCE RECOMMENDATIONS

Washing		Ironing	Tumble- dry	Dry cleaning	
Up to 60°C/140°F		On reverse side only	Yes	Yes	
Storage life					

Away

from

sunlight

Dry room with

15°C-30°C/

59°F-86°F

Care and maintenance:

- ✓ Always respect the garments' instructions.
- √ Wait 24 hours after the application before the first wash.
- ✓ Avoid the use of aggressive products.

Washing recommendations:

- ✓ Respect the textile recommendations.
- ✓ Preferably inside out to extend the design's life.
- ✓ Do not bleach.

Vertical

position